



## LOCAL NOTICE TO MARINERS No. 16 of 2016

### Recovery of Seasonal Race Buoys and Re-lit Navigation Marks Off Littlehampton Harbour

**MARINERS ARE ADVISED** that seasonal race markers laid by the Arun Yacht Club in the vicinity of Littlehampton Harbour have now been recovered.

Name	Position (WGS84)	Relative Bearing (from Drum Head West Beacon Light)
Omar (ivo. Winter Knoll)	50° 46.32'N 00° 33.15'W	1.6nm, bearing of 196°
West	50° 47.52'N 00° 30.00'W	1.2nm, bearing of 235°
Steel Can	50° 47.18'N 00° 34.03'W	1.6nm, bearing of 103°

In addition, lights marking the Arun District Council Meteorological Mast and Southern Water Outfall Buoy have been re-lit.

Name	Position (WGS84)	Relative Bearing (from Drum Head West Beacon Light)	Characteristics	Owner
Arun District Council Met Mast	50° 46.180'N 00° 29.550'W	2.5nm, bearing of 133°	Fl(5)Y.20s9m5M	ADC
Outfall Buoy	50°46.240'N 0°30.560'W	2.0nm, bearing of 144°	Fl.Y.5s	Southern Water

Mariners should also be aware that the temporary buoy laid adjacent to the wall collapse in Arundel has now been removed. All vessels transiting the stretch of river between the A27 Arundel Bypass bridge and the Old Arundel bridge in the town centre at Queen Street should be navigated at DEAD SLOW and with NO WASH until further notice.

**Owners, Agents, Charterers, Marinas, Yacht Clubs and Recreational Sailing Organisations should ensure that the contents of this Notice are made known to the masters or persons in charge of their vessels or craft.**

Billy Johnson  
Harbour Master

16<sup>th</sup> November 2016

**LOCAL NOTICE TO MARINERS No. 16 of 2016**

