


LOCAL NOTICE TO MARINERS No. 13 of 2019

Littlehampton Outfall Buoy Unlit

MARINERS ARE ADVISED that the Littlehampton Outfall Buoy is currently unlit and awaiting replacement parts.



Owners, Agents, Charterers, Marinas, Yacht Clubs and Recreational Sailing Organisations should ensure that the contents of this Notice are made known to the masters or persons in charge of their vessels or craft.

Harry Gregory
Deputy Harbour Master

28th October 2018